



Griffin Display

display shown with all segments illuminated

Calibration Set Points:

- 1 - Ground (Zero Set Point)
- 2 - Optimum Alpha Angle (OAA) ($1.3 \times V_s$)
- 3 - Cruise Alpha (V_a or Maneuvering Speed)