


# Increasing AOA to Display Indications



**Falcon Display**

*display shown with all segments illuminated*

### Calibration Set Points:

- 1 - Ground ( Zero Set Point )
- 2 - Optimum Alpha (  $1.3 \times V_s$  )
- 3 - Cruise Alpha (  $V_a$  or  $1.9 \times V_s$  )